



# Comment Summary

**Application #:** PL202300208

**Address:** 4801 AMERICAN BLVD W, BLOOMINGTON, MN 55437

**Request:** Uniform Sign Design for Luther Hyundai located at 4801 American Blvd. W.

---

**Fire Department Review Contact:** Laura McCarthy at [lmccarthy@BloomingtonMN.gov](mailto:lmccarthy@BloomingtonMN.gov), (952) 563-8965

- 1) Ensure FDC and other exterior life safety equipment is unobstructed and clearly visible from the emergency vehicle access lane.
- 2) Building/property shall be adequately signed for emergency response.

**Public Works Review Contact:** Brian Hansen at [bhansen@BloomingtonMN.gov](mailto:bhansen@BloomingtonMN.gov), (952) 563-4543

- 1) Pylon sign may not be located within 15ft clearview triangle. Field verify prior to installation.